


# Part alignment - plane and two circles (non-CAD)



© 2013 Renishaw plc. All rights reserved.

Renishaw® is a registered trademark of Renishaw plc.

This document may not be copied or reproduced in whole or in part, or transferred to any other media or language, by any means, without the prior written permission of Renishaw.

The publication of material within this document does not imply freedom from the patent rights of Renishaw plc.

### **Disclaimer**

Considerable effort has been made to ensure that the contents of this document are free from inaccuracies and omissions. However, Renishaw makes no warranties with respect to the contents of this document and specifically disclaims any implied warranties. Renishaw reserves the right to make changes to this document and to the product described herein without obligation to notify any person of such changes.

### **Trademarks**

All brand names and product names used in this document are trade names, service marks, trademarks, or registered trademarks of their respective owners.

## **Part alignment - plane and two circles (non-CAD)**

## Care of equipment

Renishaw probes and associated systems are precision tools used for obtaining precise measurements and must therefore be treated with care.

## Changes to Renishaw products

Renishaw reserves the right to improve, change or modify its hardware or software without incurring any obligations to make changes to Renishaw equipment previously sold.

## Warranty

Renishaw plc warrants its equipment for a limited period (as set out in our Standard Terms and Conditions of Sale) provided that it is installed exactly as defined in associated Renishaw documentation.

Prior consent must be obtained from Renishaw if non-Renishaw equipment (e.g. interfaces and/or cabling) is to be used or substituted. Failure to comply with this will invalidate the Renishaw warranty.

Claims under warranty must be made from authorised service centres only, which may be advised by the supplier or distributor.

## Trademarks

Windows 98, Windows XP, Windows 2000 and Windows NT are registered tradenames of the Microsoft Corporation.

IBM is the tradename of the International Business Machines Inc

All trademarks and tradenames are acknowledged.

## Contents

1	Part alignment - plane and two circles (non-CAD) .....	6
1.1	Tutorial pre-requisites.....	6
1.2	Tutorial objectives.....	6
2	Introduction.....	7
3	Create a new program.....	8
4	Measure a plane and two circles.....	13
5	Defining primary, secondary and tertiary datums.....	18

# **1 Part alignment - plane and two circles (non-CAD)**

## **1.1 Tutorial pre-requisites**

- The student should understand 'Principles of part alignment'
- The student should have covered 'Part alignment - plane, line and point'

## **1.2 Tutorial objectives**


- Introduction to feature constructions
- Understand alternative part alignment options

## 2 Introduction

In this tutorial, the Renishaw training block will be used to simulate part alignment requirements controlled by a central boss / bore and timing feature (e.g. a rotating part).


### 3 Create a new program

Before measurements can be made a program must be created.




This will allow settings to be confirmed before the program is created,

After clicking 'Browse', select a suitable location for the program:






**GUIDANCE NOTE:** It is recommended that the new program be placed in its own folder. This will make it easier to locate related files that are generated during programming / measurement output.




The 'New Inspection' dialogue will now open:



**GUIDANCE NOTE:** Further information on this dialogue window will be provided later in the 'Basic options within the new inspection dialogue' tutorial.

The following header will be inserted into the program:




```

000001 DMISMN/'Start Template',05.2
000002 FILNAM/'Start Template',05.2
000003 DV(0)=DMESWU/'13,1,2,212'
000004 UNITS/MM,ANGDEC
000005 DECPL/ALL,DEFAULT
000006 U(0)=UFORM/ALL,PLOT
000007 DISPLV/TERM,U(0),STOR,DMIS,U(0)
000008 SNSET/APPRCH,5
000009 SNSET/CLRSRF,15
000010 SNSET/DEPTH,0
000011 D(0)=DATSET/MCS
000012 MODE/MAN
000013 T(CORTOL_X1)=TOL/CORTOL,XAXIS,-0.1,0.1
000014 T(CORTOL_Y1)=TOL/CORTOL,YAXIS,-0.1,0.1
000015 T(CORTOL_Z1)=TOL/CORTOL,ZAXIS,-0.1,0.1
000016 T(DIAM_1)=TOL/DIAM,-0.1,0.1
000017 PAUSE
000018 ENDFIL
  
```

To insert some line spaces to make the program easier to read, right mouse click on the line containing the 'Pause' command:

```

000015 T(CORTOL_Z1)=TOL/CORTOL,ZAXIS,-
000016 T(DIAM_1)=TOL/DIAM,-0.1,0.1
000017 PAUSE
000018 ENDFIL
  
```



Select: Insert Command.



Put a space in the window.

Click: 'OK' to close and insert the line.


The line is inserted above the line that was selected.

Add more spaces as required.


```

000008 SNSET/APPRCH,5
000009 SNSET/CLRSRF,15
000010 SNSET/DEPTH,0
000011 D(0)=DATSET/MCS
000012 MODE/MAN
000013 T(CORTOL_X1)=TOL/CORTOL,XAXIS,-0.1,0.1
000014 T(CORTOL_Y1)=TOL/CORTOL,YAXIS,-0.1,0.1
000015 T(CORTOL_Z1)=TOL/CORTOL,ZAXIS,-0.1,0.1
000016 T(DIAM_1)=TOL/DIAM,-0.1,0.1
000017
000018
000019
000020
000021
000022 PAUSE
000023 ENDFIL
  
```


Next define the work plane that contains the features that will be measured:




**GUIDANCE NOTE:** It is particularly important to define a work plane when working in polar coordinates because it defines which plane will use the polar coordinate system.




Before sensors can be selected they must have been recalled into the part program. To recall the tool:




Select the appropriate tool from the drop down menu.



The sensor can now be selected. To select the tool:



The tool should be displayed in the window, if not, select it from the drop down menu.



```

000012  M0DE/MAN
000013  T(CORTOL_X1)=TOL/CORTOL,XAXIS,-0.1,0.1
000014  T(CORTOL_Y1)=TOL/CORTOL,YAXIS,-0.1,0.1
000015  T(CORTOL_Z1)=TOL/CORTOL,ZAXIS,-0.1,0.1
000016  T(DIAM_1)=TOL/DIAM,-0.1,0.1
000017
000018  RECALL/SA(PH10_PAA1_TP200_D3x20.1.20.2.A0.0-B0.0)
000019  SNSLCT/SA(PH10_PAA1_TP200_D3x20.1.20.2.A0.0-B0.0)
000020  ▶
000021
000022
000023  PAUSE
000024  ENDFIL

```

The program will now have two additional lines which recalls and selects the tool.

Feature measurement can now take place.


## 4 Measure a plane and two circles

Before any meaningful measurement is made on a part it must first be **ALIGNED**.


This must be done as the part will not be sitting square to any axis of the CMM and therefore will be generating errors that do not exist into the measured results.

A good example of this is shown below where the effects on an **UNALIGNED** part can be seen.

**GOOD - The part has been aligned:**





**BAD - The part has NOT been aligned:**




As can be seen the result of an unaligned or badly aligned part will result in an **ELLIPSE** and not a **CIRCLE** as required.


Firstly, the top face of the training block will be inspected as a plane.




Take a minimum of three points on the plane:




To create a primary axis on this feature click 'Datum' then select 'One Axis':






**GUIDANCE NOTE:** The secondary and tertiary panes are unavailable because 'One Axis' datum was selected.


To fully constrain the part, two circles will also be inspected.




Click: 'Apply' to complete the measuring cycle.



Click: 'Inspect'.




Select: 'Circle'.





Take a minimum of three points in circle 2:

Click: 'Apply' to complete the measuring cycle.





To create a feature that can be used to lock the rotation (about Z) of the component, a line will be constructed between the centres of the two measured lines.



**GUIDANCE NOTE:** Make a note of the order the holes have been inserted in the construction window:

i.e. CIR001 to CIR002 will give a positive direction, and CIR002 to CIR001 will give a negative direction.

This is important when selecting the axis direction for alignment.

**Click:** 'Apply' to complete the construction cycle.

Code Produced :-

```
F(LINE001)=FEAT/LINE,UNBND,CART,57.5,20.13,-40,0,-1,0,-1,0,0
CONST/LINE,F(LINE001),BF,FA(CIR001),FA(CIR002)
```

## 5 Defining primary, secondary and tertiary datums

There are now enough features to create a datum.

**Click: 'Datum'.**

**Select: 'Three Axes'.**

**Give the new datum a label.**

**Click: 'OK' to complete the procedure.**

**In this case PLN001 is the PRIMARY AXIS [ +Z ]**

**LINE001 is the SECONDARY AXIS [ +Y ] (No origin here)**

**CIR001 is the TERTIARY point origin [ X and Y ]**


**In this case the constructed line lies along the Y axis.**

**NOTE:** There is also the option of selecting +X/-X or -Y.

The 'Create Datum' dialog box is shown with the following settings:

- Datum label:** MAIN
- Primary:**
  - Label: A
  - Feature: PLN001
  - Axis: +Z (selected)
  - Origin: Z (checked)
- Secondary:**
  - Label: B
  - Feature: LINE001
  - Axis: +Y (selected)
  - Origin: Y (checked)
- Tertiary:**
  - Label: C
  - Feature: CIR001
  - Axis: X (selected)
  - Origin: X (checked), Y (checked)

The datum should now be saved to enable it to be recalled later if necessary:



THE PART ALIGNMENT IS NOW COMPLETE AND IS READY FOR MEASUREMENT.

**NOTE:** This is a very basic manual alignment using minimum points and is not accurate enough for good metrology.

**Code generated for plane and line through two diameters**

```

DMISMN/'Start Template',05.2
FILNAM/'Start Template',05.2
DV(0)=DMESWV/'16,0,1,22'
UNITS/MM,ANGDEC
DECPL/ALL,DEFAULT
V(0)=VFORM/ALL,PLOT
DISPLY/TERM,V(0),STOR,DMIS,V(0)
SNSET/APPRCH,5
SNSET/CLRSRF,15
SNSET/DEPTH,0
D(0)=DATSET/MCS
MODE/MAN
T(CORTOL_X1)=TOL/CORTOL,XAXIS,-0.1,0.1
T(CORTOL_Y1)=TOL/CORTOL,YAXIS,-0.1,0.1
T(CORTOL_Z1)=TOL/CORTOL,ZAXIS,-0.1,0.1
T(DIAM_1)=TOL/DIAM,-0.1,0.1
WKPLAN/XYPLAN
RECALL/SA(TP20_2x20.1.20.2.A0.0-B0.0)
SNSLCT/SA(TP20_2x20.1.20.2.A0.0-B0.0)
$$<MEAS_PLANE name = "PLN001">
GEOALG/PLANE,DEFAULT,ELIMINATE,OFF,FILTER,OFF
MODE/MAN
F(PLN001)=FEAT/PLANE,CART,0,92.5,0,0,0,1
MEAS/PLANE,F(PLN001),3
PTMEAS/CART,2.86,-54.997,0,0,0,1
PTMEAS/CART,53.712,11.69,0,0,0,1
PTMEAS/CART,-52.337,16.459,0,0,0,1
ENDMES
$$<\MEAS_PLANE = PLN001>
DATDEF/FA(PLN001), DAT(A)
D(Top_Face)=DATSET/DAT(A),ZDIR,ZORIG
$$<MEAS_CIRCLE name = "CIR001">
MODE/MAN
F(CIR001)=FEAT/CIRCLE,INNER,CART,0,0,-2.309,0,0,1,80
MEAS/CIRCLE,F(CIR001),3
PTMEAS/CART,40,0,-2.309,-1,0,0
PTMEAS/CART,-20,34.641,-2.309,0.5,-0.866,0
PTMEAS/CART,-20,-34.641,-2.309,0.5,0.866,0
ENDMES
$$<\MEAS_CIRCLE = CIR001>
$$<MEAS_CIRCLE name = "CIR002">
MODE/MAN
F(CIR002)=FEAT/CIRCLE,INNER,CART,0,34.5,-10,0,0,1,7
MEAS/CIRCLE,F(CIR002),3
PTMEAS/CART,3.5,34.5,-10,-1,0,0
PTMEAS/CART,-1.75,37.531,-10,0.5,-0.866,0
PTMEAS/CART,-1.75,31.469,-10,0.5,0.866,0
ENDMES
$$<\MEAS_CIRCLE = CIR002>
F(LINE001)=FEAT/LINE,UNBDN,CART,0,17.25,-6.155,0,0.976,-0.218,0,0.218,0.976
CONST/LINE,F(LINE001),BF,FA(CIR001),FA(CIR002)
DATDEF/FA(PLN001), DAT(B)
DATDEF/FA(LINE001), DAT(C)
DATDEF/FA(CIR001), DAT(D)
D(MAIN)=DATSET/DAT(B),ZDIR,ZORIG,DAT(C),YDIR,DAT(D),XORIG,YORIG
SAVE/DA(MAIN)

```

This page intentionally left blank

**Renishaw plc**  
New Mills, Wotton-under-Edge,  
Gloucestershire, GL12 8JR  
United Kingdom

**T** +44 (0)1453 524524  
**F** +44 (0)1453 524901  
**E** [uk@renishaw.com](mailto:uk@renishaw.com)  
[www.renishaw.com](http://www.renishaw.com)

**RENISHAW**   
**apply innovation™**

**For worldwide contact details,  
please visit our main web site at  
[www.renishaw.com/contact](http://www.renishaw.com/contact)**



H - 1000 - 5312 - 01